

FIG 1




FIG 2







FIG 3a





51






FIG 3b



**FIG 4**






FIG 5








FIG 6








FIG 7



41	V		E_r	0	1	2	3	4	5	6	7
1	Q		M_r	5	5	5	5	5	5	5	6
34	V		E_r	0	1	2	3	4	5	6	7
2	Q		M_r	4	4	4	4	4	5	5	4
27	V		E_r	0	1	2	3	4	5	6	7
3	Q		M_r	3	3	4	4	4	3	3	3
36	V		E_r	0	1	2	3	4	5	6	7
3	Q		M_r	5	5	4	4	4	4	5	5
37	V		E_r	0	1	2	3	4	5	6	7
5	Q		M_r	4	5	5	5	5	5	4	4
30	V		E_r	0	1	2	3	4	5	6	7
6	Q		M_r	4	3	3	4	4	4	4	4
23	V		E_r	0	1	2	3	4	5	6	7
7	Q		M_r	3	3	3	2	3	3	3	3
32	V		E_r	0	1	2	3	4	5	6	7
0	Q		M_r	4	4	4	4	4	4	4	4

FIG 8








FIG 9








FIG 10e